


Aerial photography by Merrick and
Company, May 1980



AERIAL PHOTOGRAPH SHOWING OUTLINE OF STUDY AREA, SUBCATCHMENTS, LOCATION OF RAIN GAGES, AND MONITORING SITE FOR ROONEY GULCH
AT ROONEY RANCH, NEAR MORRISON, COLORADO